If you are replacing a 2.*x* module with a 3.*x* module and must use exact match keying in the I/O configuration, take additional action depending on your version of RSLogix 5000 software.

| If you use exact match keying and | Then you must |
|---|---|
| RSLogix 5000 software, version 13 or greater | 1. Delete the 2.*x* module from the I/O Configuration in the RSLogix 5000 project.<br>2. Add a new 3.*x* revision module to the I/O configuration. |
| RSLogix 5000 software, version 12 or lower | Do one of the following:<br>• Change the module's configuration to Disable Keying.<br><br>• Upgrade RSLogix 5000 software to version 13 or greater and complete the steps listed for RSLogix version 13 or greater. |

## Additional Resources

For more information about changing module's I/O configuration, see the Digital I/O User Manual, publication 1756-UM058.

You can view or download publications at http://literature.rockwellautomation.com. To order paper copies of technical documentation, contact your local Rockwell Automation distributor or sales representative.