

If you are replacing a 2.x module with a 3.x module and must use exact match keying in the I/O configuration, take additional action depending on your version of RSLogix 5000 software.

If you use exact match keying and	Then you must
RSLogix 5000 software, version 13 or greater	<ol style="list-style-type: none">1. Delete the 2.x module from the I/O Configuration in the RSLogix 5000 project.2. Add a new 3.x revision module to the I/O configuration.
RSLogix 5000 software, version 12 or lower	<p>Do one of the following:</p> <ul style="list-style-type: none">• Change the module's configuration to Disable Keying.• Upgrade RSLogix 5000 software to version 13 or greater and complete the steps listed for RSLogix version 13 or greater.

Additional Resources

For more information about changing module's I/O configuration, see the Digital I/O User Manual, publication 1756-UM058.

You can view or download publications at <http://literature.rockwellautomation.com>. To order paper copies of technical documentation, contact your local Rockwell Automation distributor or sales representative.