



## **Release Note**

# **ControlLogix Digital I/O Modules**

### **Before You Begin**

---

**IMPORTANT**

**Do not backflash your module's firmware from firmware revision 3.x to 2.x.** Attempting to backflash or downgrade a module's firmware from 3.x to 2.x will irreversibly damage the module.

You must return modules damaged by an attempt to backflash to firmware 2.x to Rockwell Automation.

---

In addition, attempting to upgrade a 2.x module to 3.x results in a ControlFlash error dialog. Upgrading a module's 2.x firmware to 3.x firmware is not supported.

### **About This Publication**

This publication is for use with all 1756 Digital I/O modules. It contains important information about module revisions and their corresponding firmware.